

Attention to gas cock with air vent port and replacement

December 22, 2016
Tokyo Gas Co., Ltd.

Tokyo Gas has installed the “gas cock with air vent port” inside the cabinet placed under gas cook-top at some customers sites from September 1991 to January 2004. There was a slight combustion due to small gas leak inside the “draw-type cabinet” at the customer’s home on 23rd November 2016, but no physical injury and property damage.

We have decided to replace this type of gas cock for the gas cock without air vent port in order to make sure of safety.

- Number of customers targeted

- (1) Customers targeted

Customers installed the “gas cock with air vent port” inside cabinet from September 1991 to January 2004 and using built in kitchens with “draw-type cabinet”

- (2) Number of customers targeted

Approx. 0.45 million customers